

FAST AFR. RPT

DESPATCH

No. 10999

0909

APR 25

261

(Subject.)

Uganda Railway Water Supply - Boring Operations

1905

Manager having reached 200 ft wishes to continue to 350 ft, hopes to be able to pierce hard stratum. Possibly water is below as stratum has good dip.

(Remarks)

Mr. Contractor

The consulting engineers after inspection of a specimen of the material advised that boring should not be continued. But it is not likely they are experts on this subject, which is one for judgment with the engineer. As it is very desirable to get water here for the railway, it should be indicated to what extent manager go on to 350 ft.

By telegraph.

M. J. R. 6/4

at me.

M. J. R. 13/1

11635

C.O.
10999
Rec'd
5 APR 35

Ch
Telegram

Sir Donald Stewart to Mr Lyttelton.

26

(Received, Colonial Office, 3.10 p.m. 5th April, 1935).

No. 102.

Your telegram No. 75 Manager having reached 200 feet wishes to continue to 350 feet; hopes to be able to pierce hard stratum. Possibly water is below as stratum has good dip.

